



# Carbon Removal

# on Twin Plastiblow PB2000 Blow Moulding Machine

## The Process

PVC Purge extruding through head





Carbon evidence (Left) Clean of carbon (Right)







"Best I have ever seen" 42-year-experienced technician



## Results

#### Normal results:

- Strip down to clean monthly
- 8 hours, overtime x 2 people/month
- 1 hour purge out
- 1 hour start up

#### Aquapurge results:

- 12 kg PVC Purge
- 45 minutes

#### One Year On:

- 192 overtime hours saved
- 83 production hours saved
- No strip down required
- 5 kg to shut down (10 minutes)
- 10 minutes start up

### Be amazed and request your FREE trial today

Aquapurge Ltd, Unit 2, Argent Trade Park, Pump Lane, Hayes, Middlesex UB3 3NB