


## Degraded PVC Removal on 75mm Hose Cross Head Extrusion Line

### The Process



Material supplier issue caused  
massive degradation

---



25 kg PVC Purge shows how it  
scrubs the carbon off

---



### Results

---

#### Normal results:

- Complete strip down
- 4 hours cleaning

#### Aquapurge results:

- 25 kg PVC Purge
- Screw, barrel and adaptor
- 30 minutes
- Surface cleaner than  
a manual clean

**Be amazed and request your FREE trial today**

Aquapurge Ltd, Unit 2, Argent Trade Park, Pump Lane, Hayes, Middlesex  
UB3 3NB

☎ +44 (0) 20 8813 7990    ✉ enquiries@aquapurge.com

[www.aquapurge.com](http://www.aquapurge.com)